

T O P S E C R E T

IN 85196

OPS 10 40

T O P S E C R E T 061015Z CITE [REDACTED]

25X1A

IMMEDIATE [REDACTED]

INFO [REDACTED]

A. EX6843

B. CAMERA ON & OFF REPORT

C. TYPE 1:

(1)	(2)	(3)	(4)	(5)
-5	011650	2116	12325	714
-3	011701	2114	12324	720
-1	011711	2114	12323	731
0001	015519	1247	10747	787
0003	NR	NR	NR	NR
0005	015531	1244	10742	788
0007	015537	1242	10739	788
767	022443	2009	10145	657
769	022449	2007	10144	643
771	022455	2004	10142	629
773	031125	1714	NR	88
775	NR	NR	NR	NR
777	NR	NR	NR	NR
1561	NR	NR	NR	NR
1563	034215	1708	11016	747
1565	034222	1709	11019	748

D. CAMERA CAGED INDICATOR APPEARS PERIODICALLY THROUGHOUT MISSION.

CLOCK APPEARS IN IMAGE AREA PERIODICALLY THROUGHOUT MISSION.

T O P S E C R E T

TOR: 061051Z JAN 68

T O P S E C R E T

Approved For Release 2002/06/13 : CIA-RDP69B00041R001500030014-5

25X1A

Next 6 Page(s) In Document Exempt

Approved For Release 2002/06/13 : CIA-RDP69B00041R001500030014-5

TOP SECRET

Poster

1	10
2	11
3	12
4	13
5	14
6	15
7	16
8	17

IN 8547

OPS 1-1603

TOP SECRET 052232Z CITE

CITE

25X1A

IMMEDIATE

A. BX 6843

B. INS TAPE EVALUATION REPORT

C. INS #17

D. 74/1125 B

E. 1. SATISFACTORY

2. SATISFACTORY

3. SATISFACTORY

4. SATISFACTORY

5. SATISFACTORY

6. SATISFACTORY

7. BETWEEN ELAPSED TIMES 13096 AND 13165, 13169, AND

13192, THE TENTHS DIGIT IN THE ROLL RECORDS WAS MISSING.

BETWEEN ELAPSED TIMES 13247 AND 13262 THERE WERE TWO LINES

WHERE THE TENTHS DIGIT IN THE ROLL RECORD WAS MISSING.

8. SATISFACTORY

9. SATISFACTORY


10. SATISFACTORY

F. TAPE APPEARS GENERALLY SATISFACTORY. TAPE EVALUATION

PERTAINS TO CAMERA OPERATION ONLY.

TOP SECRET TOR:
052243Z JAN 68

TOP SECRET



CLASSIFIED MESSAGE

ROUTING

DATE

TOP SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO :

FROM :

ACTION:

INFO :

POST ID

IN 85745

OPS 1-18 93

TO

INFO

CITE

TOP SECRET 052145Z CITE

IMMEDIATE

OXCART

A. BK6843

B. FLASH REPORT AFTER PROCESSING

C. TYPE I

D. C

E. THE FILM ARRIVED IN GOOD PHYSICAL CONDITION WITH NORMAL EXPOSURE, MEDIUM CONTRAST, AND GOOD RESOLUTION. DATA RECORDING WAS OPERATIONAL IN FWD POSITION, AND INTERMITTANT IN THE AFT POSITION WITH 75 TO 100 CHAMBERS ABSENT. CAMERA STARTUP AND SHUT-DOWN NORMAL WITH RECYCLE OCCURRING THROUGHOUT 40 FRAMES, 50 0/0 INTO MISSION. DATA CHAMBERS WERE SLANTED APPROXIMATELY 6 DEGREES. TO THE LEFT OF BIAS CAUSING SOME DATA CHAMBERS TO ENTER IMAGERY UP TO 1/16". TWO MINUS DENSITY LINES, 1/16" APART AND 3 3/4" FROM TRAILING EDGE AND ONE MINUS DENSITY LINE 1 1/4" FROM LEADING

TOP SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

25X1A

IN 85045



T O P S E C R E T

PAGE 2

EDGE OCCURING ON ALL FVD GRAMES. A MINUS DENSITY LINE WAS NOTED
2 1/2 INCHES FROM LEADING EDGE ON ALL AFT FRAMES. HEAVY YELLOW
DISCOLORATION SIMILAR TO EX6842 PRESENT IN THE FILM. DISCOLORATION
WAS NOT NOTED ON IDENT MATERIAL PRESPLICED ONTO MISSION MATERIAL.
ALSO PRESENT WAS AN ORANGE PEEL EFFECT ON THE FLLM.

T O P S E C R E T TOR: #52229Z JAN 68

T O P S E C R E T